


Three-terminal device, no diode! Vcc is not isolated, what results in excessive power consumption when injected by chipflasher.



| | | | |
|-------|------------------------------------|--|---------------------------|
| | | Zerocat Flash Access | |
| | | Interfacing BIOS Chips in Hardware Protection Mode | |
| | | git://zerocat.org/zerocat/projects/zerocat-flash-access | |
| TITLE | | REVISION: | v0.4.3-0-3c0d96e (master) |
| FILE: | t60-spi-flash-connector-page03.sch | DRAWN BY: | kmx |
| PAGE | OF | | |